

## **Region 3 GPRA Baseline RCRA Corrective Action Facility**

# **Fruehauf Corp.**

**Route 119 North  
Uniontown, PA 15401  
Congressional District 20  
EPA ID #: PAD004338646  
Last Updated 6/30/2005**

## **Current Progress at the Site**

---

This facility is one of EPA Region III's high priority RCRA corrective action sites. Fruehauf is no longer in operation. A former hazardous waste lagoon was clean closed in 1984. The site is owned by Briar Hill Steel. In November, 2001 an environmental indicator inspection was done. A draft (December, 2001) EI report is under review by the state.

EPA will evaluate the data in the report upon receipt from the state. If releases are identified, EPA will determine if a facility investigation or clean-up measures are necessary to protect human health and the environment.

## **Site Responsibility**

---

RCRA Corrective Action activities at this facility are being conducted under the direction of EPA Region 3 with assistance from the State.

## **Institutional Controls**

---

Institutional controls are not required at this time.

## **Government Contact**

---

EPA Branch Chief  
Mr. Paul Gotthold - 3WC22  
U.S. Environmental Protection Agency - Region III  
1650 Arch Street  
Philadelphia, PA 19103-2029  
Phone: (215) 814-3410  
Email: [gotthold.paul@epa.gov](mailto:gotthold.paul@epa.gov)

Kathy Watson  
Operations Supervisor  
PADEP  
400 Waterfront Drive  
Pittsburgh, PA 15222  
Phone: (412) 442-4140  
Email: [kawatson@state.pa.us](mailto:kawatson@state.pa.us)

For more information about EPA's corrective action webpage, including Environmental Indicators, please visit our site at: [www.epa.gov/reg3wcmd/correctiveaction.htm](http://www.epa.gov/reg3wcmd/correctiveaction.htm)

